





### TECHNICAL INFORMATION




Approx. 6-8 threads



**Form A**

6-8 Threads Lead,  
for short through holes


Approx. 4-5 threads



**Form B**

4-5 Threads Lead with Spiral Point,  
for through holes


Approx. 2-3 threads



**Form C**

2-3 Threads Lead,  
for blind holes


Approx. 4-5 threads



**Form D**

4-5 Threads Lead,  
for through and blind holes


Approx. 2-3 threads



**Form C/35° RSP**

2-3 Threads Lead,  
35° Spiral Flute, for blind holes

Approx. 4-5 threads



**Form B-AZ**

4-5 Threads Lead with Spiral Point  
and interrupted threads for through  
holes

